

# M A T E R I A L   S A F E T Y   D A T A   S H E E T

KOLENE CORPORATION - 12890 Westwood Ave. - Detroit, Michigan 48223  
24 HOUR EMERGENCY PHONE: 313-273-9220

Page: 3

## REACTIVITY DATA

STABILITY - Under normal conditions, the material is stable.

INCOMPATIBILITY IN STORAGE - Avoid direct contact with organic materials, concentrated acids, reducing agents, magnesium, tin, zinc, aluminum and alloys of these metals and flammable or combustible material.

HAZARDOUS DECOMPOSITION PRODUCTS - Under conditions of extreme heat this product may generate oxides of nitrogen.

## SPECIAL PRECAUTIONS

### 1. PROTECTIVE EQUIPMENT:

- a. Respiration protection not required under normal use.
- b. EYE - Face shield and goggles should be worn.
- c. GLOVES - Manufacturer recommended gloves for handling corrosive materials should be worn.
- d. OTHER CLOTHING AND EQUIPMENT - Safety shoes or rubber boots, clothing fitted to avoid areas of skin exposure or residue retention.

### 2. SAFETY SHOWERS AND EYEWASH STATIONS SHOULD BE AVAILABLE IN WORK AREAS.

### 3. IN CASE OF ACCIDENTAL LEAK, MATERIAL SHOULD BE RETAINED IN SUITABLE CONTAINERS OR HOLDING AREA. RECOVER WITH VACUUM EQUIPMENT, OR IF UNAVAILABLE, CAREFULLY NEUTRALIZE WITH ACID. IN ALL CASES, PROTECTIVE CLOTHING AND RESPIRATOR PROTECTION SHOULD BE USED BY CLEAN-UP PERSONNEL. SAFE HANDLING PRACTICES AS OUTLINED SHOULD BE FOLLOWED: AREA OF SPILL SHOULD BE FLUSHED WITH WATER TO REMOVE NON-VISIBLE RESIDUES. FOLLOW NORMAL DISPOSAL PRACTICE WITH RINSE WATER ACCORDING TO FEDERAL, STATE, AND LOCAL REGULATIONS.

### 4. PRECAUTIONARY STATEMENTS:

DANGER! CORROSIVE AND OXIDIZER.  
CAUSES SEVERE BURNS TO SKIN AND EYES.  
USE ONLY UNDER DESCRIBED CONDITIONS.  
DO NOT GET IN EYES, ON SKIN, OR CLOTHING.  
DO NOT TAKE INTERNALLY.  
DO NOT BREATHE DUST OR MIST.  
WEAR RECOMMENDED PROTECTIVE CLOTHING WHEN HANDLING.  
WASH THOROUGHLY AFTER HANDLING.

### 5. The intended use of this material is in the fused form and in this application adequate exhaust facilities should service the fusing area to avoid circulation of mists, carbon dioxide and oxides of nitrogen.

REMARKS